


# Margins & borderless

LETTER | 100% / Actual size

Low ink | Frames at 0 / 3 / 5 / 10 mm from each paper edge

Inspect where edge marks disappear; that is the printable-area boundary.

Do not enable borderless enlargement when measuring margins.



30 mm square

Screen previews cannot reveal the printer hardware margin.

MG-01 v2 | LETTER | margin frames

Graph Paper Printable | Physical printer validation pending

[graphpaperprintable.org/r/MG-01/](http://graphpaperprintable.org/r/MG-01/)

